

# **Cummins Warranty**

**Latin America, Mexico, Australia/New Zealand, And South Africa  
Automotive ISG Engines Warranty**

## Coverage

### Products Warranted

This Warranty applies to new ISG Engines sold by Cummins and delivered to the first user on or after February 1, 2016, that are used in automotive on-highway applications in Latin America\*, Mexico, Australia/New Zealand, and South Africa\*\*, except for Engines used in bus and coach applications for which different Warranty Coverage is provided.

### Base Engine Warranty

The Base Engine Warranty covers any failures of the Engine which result, under normal use and service, from a defect in material or factory workmanship (Warrantable Failure). This Coverage begins with the sale of the Engine by Cummins and ends two years or 250,000 miles (402,336 kilometers) or 6,250 hours of operation, whichever occurs first, after the date of delivery of the Engine to the first user.

Failures of fuel injectors are covered for two years or 125,000 miles (201,168 kilometers) or 3,125 hours, whichever occurs first, after the date of delivery of the Engine to the first user.

### Extended Major Components Warranty

The Extended Major Components Warranty covers Warrantable Failures of the following Engine parts or castings:

Accessory Drive Adjustable Idler Gear	Exhaust Rocker Lever
Accessory Drive Lower Idler Gear	Forging
Accessory Drive Upper Idler Gear	Gear
Bolt/Capscrew	Injector Lobe
Brake Lobe	Intake Rocker Lever
Camshaft Gear	Low C Bore/Pkg Rg Bore
Camshaft Nose	Main Bearing Cap
Camshaft Other Than Nose	Roller Pin
Cap	Roller
Capscrew	Valve Lobe
Dowel Pin/Ring	Valve Rocker Shaft
Drive Gear	

Bushing and bearing failures are NOT covered.

This Coverage begins with the expiration of the Base Engine Warranty and ends five years, 500,000 miles (804,672 kilometers) or 12,500 hours, whichever occurs first, after the date of delivery to the first user.

**These Warranties are made to all Owners in the chain of distribution and Coverage continues to all subsequent Owners until the end of the periods of Coverage.**

### Cummins Responsibilities During The Base Engine Warranty

Cummins will pay reasonable costs for towing a vehicle disabled by a Warrantable Failure to the nearest authorized repair location. In lieu of the towing expense, Cummins will pay reasonable costs for mechanics to travel to and from the location of the vehicle, including meals, mileage and lodging, when the repair is performed at the site of the failure.

### During The Base Engine And The Extended Major Components Warranties

Cummins will pay for all parts and labor needed to repair the damage to the Engine resulting from a Warrantable Failure.

Cummins will pay for the lubricating oil, antifreeze, filter elements, belts, hoses and other maintenance items that are not reusable due to a Warrantable Failure.

Cummins will pay for reasonable labor costs for Engine removal and reinstallation when necessary to repair a Warrantable Failure.

## Owner Responsibilities

Owner is responsible for the operation and maintenance of the Engine as specified in the applicable Cummins Operations and Maintenance Manual. Owner is also responsible for providing proof that all recommended maintenance has been performed.

Before the expiration of this Coverage, Owner must notify a Cummins distributor, authorized dealer or other repair location approved by Cummins of any Warrantable Failure and make the Engine available for repair by such facility. Except for Engines disabled by a Warrantable Failure during the Base Engine Warranty period, Owner must also deliver the Engine to the repair facility. Service locations are listed on the Cummins Worldwide Service Locator at cummins.com.

Owner is responsible for the cost of lubricating oil, antifreeze, filter elements and other maintenance items provided during Warrantable repairs unless such items are not reusable due to the Warrantable Failure.

Owner is responsible for communication expenses, meals, lodging and similar costs incurred as a result of a Warrantable Failure.

Owner is responsible for non-Engine repairs, "downtime" expenses, cargo damage, fines, all applicable taxes, all business costs and other losses resulting from a Warrantable Failure.

## Limitations

Engines with an emissions certification listed below must be operated using only diesel fuel having no more than the corresponding maximum sulfur content. Failure to use the specified fuel as listed in the Cummins Fuel Bulletin #3379001 Table 1 (Cummins Inc. Required Diesel Fuel Specifications) can damage the Engine and aftertreatment system within a short period of time. This

damage could cause the Engine to become inoperable and failures attributable to the use of incorrect fuels will be denied Warranty Coverage. Fuel specifications also need to comply with local fuel regulations (EN590 for Europe and ASTM D975 for North America) for Warranty eligibility.

**Maximum sulfur levels by emissions certification level as listed on the Engine's dataplate are:**

EPA 2007/2010/2013/2017/2021/2024	max. 15 parts per million
EPA Tier 4 Interim / Final / Stage V in North America	max. 15 parts per million
EU Stage IIIB 2011	max. 15 parts per million
EU Stage IV 2011	max. 15 parts per million
EU Stage V	max. 10 parts per million
Euro 4/5	max. 50 parts per million
Euro 6	max. 10 parts per million

Cummins is not responsible for failures or damage resulting from what Cummins determines to be abuse or neglect, including, but not limited to: operation without adequate coolants or lubricants; overfueling; overspeeding; lack of maintenance of lubricating, cooling or intake systems; improper storage, starting, warm-up, run-in or shutdown practices; unauthorized modifications of the Engine.

Cummins is also not responsible for failures caused by incorrect oil or fuel or by water, diesel exhaust fluid, catalytic reagent, dirt or other contaminants in the fuel, oil, diesel exhaust fluid, catalytic reagent or intake air system.

Failures resulting in excessive oil consumption are not covered beyond the Base Engine Warranty. Before a claim for excessive oil consumption will be considered, Owner must submit adequate documentation to show that consumption exceeds Cummins published standards.

Failures of belts and hoses supplied by Cummins are not covered beyond the first year after the date of delivery of the Engine to the first user or the duration of the Warranty, whichever occurs first.

Parts used to repair a Warrantable Failure may be new Cummins parts, Cummins approved rebuilt parts or repaired parts. Cummins is not responsible for failures resulting from the use of parts not approved by Cummins.

A new Cummins or Cummins approved rebuilt part used to repair a Warrantable Failure assumes the identity of the part it replaced and is entitled to the remaining Coverage hereunder.

Cummins Inc. reserves the right to interrogate Electronic Control Module (ECM) data for purposes of failure analysis.

**CUMMINS DOES NOT COVER WEAR OR WEAROUT OF COVERED PARTS.**

**CUMMINS IS NOT RESPONSIBLE FOR INCIDENTAL OR CONSEQUENTIAL DAMAGES.**

**THIS WARRANTY AND THE EMISSION WARRANTY SET FORTH HEREINAFTER ARE THE SOLE WARRANTIES MADE BY CUMMINS IN REGARD TO THESE ENGINES. CUMMINS MAKES NO OTHER WARRANTIES, EXPRESS OR IMPLIED, OR OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.**

This Warranty gives you specific legal rights, and you may also have other rights which vary from country to country.

In the case of consumer sales, in some countries the Owner has statutory rights which cannot be affected or limited by the terms of this Warranty.

Nothing in this Warranty excludes or restricts any contractual rights the Owner may have against third parties.

\* Latin America includes only Argentina, Bolivia, Chile, Colombia, Costa Rica, Dominican Republic (Santo Domingo only), Ecuador, El Salvador, Guatemala, Honduras, Mexico, Nicaragua, Panama, Paraguay, Peru, Uruguay and Venezuela.

\*\* South African countries include: Botswana, Kenya, Namibia, Malawi, Mozambique, Zimbabwe, Tanzania, Zambia and the Republic of South Africa (RSA).



Cummins Inc.  
Box 3005  
Columbus, IN 47202-3005  
U.S.A.

Bulletin No. 5410612  
Printed in U.S.A. Rev 8/23  
©2017 Cummins Inc.